

**Table 7: Sites Where Source Control Effectiveness
Has Been Assessed or Controlled**

Name	Address	Status
American Avionics King County Airport	7023 Perimeter Rd S	Restrictive Covenant, Institutional Controls in place
Arco Station # 5218	7200 E Marginal Way S	Gasoline and benzene in groundwater. Cleanup conducted. Groundwater monitoring ongoing.
Boeing Electronic Manufacturing	7300 Perimeter Rd S	Cleanup of chlorinated VOCs under VCP, groundwater not a source to Slip 4
Boeing N Field F & G Facility	7500 E Marginal Way S	LUST Reported Cleaned Up
Boeing N Field Green Hornet Area	7500 E Marginal Way S	LUST Reported Cleaned Up
Boeing North Field Bldg 3-374	7500 E Marginal Way S	LUST Reported Cleaned Up
Boeing North Field Delivery	7500 E Marginal Way S	LUST Reported Cleaned Up
Clay Lacy Aviation (former Flightcraft Inc.)	8285 Perimeter Rd S	NFA after assessment, IRAP, or VCP
Federal Express King Co. Airport	7607 Perimeter Rd	LUST Reported Cleaned Up
First South/Crowley Maritime/Boeing S Bank	Slip 4, 7400 8th Ave. S	Ecology contractor sampled for bank/soil/sediment PCBs in July 2005. Results indicate no major ongoing source, and no need for a major upland cleanup. Low PCB levels in bank/soil/sediments will be addressed as part of the sediment cleanup/bank stabilization action.
King County Airport Maintenance	6518 Ellis Ave S	Cleaned up under prior authority (pre-MTCA), LUST Reported Cleaned Up
Puget Sound Energy	6349 18th Ave S	Gasoline UST removed. Clean closure. All contamination removed.
WA Air National Guard	6736 Ellis Ave S	Remediation of chlorinated solvents complete. NFA after assessment, VCP